

3D打印机A8装配零件清单表


序号	图片	零件名称	数量	核对	序号	图片	零件名称	数量	核对
1-1		热床固定板	1		2-1		主板	1	
1-2		220mm*220mm*3mm 铝基板加热平台	1		2-2		左Z轴丝杆螺母支撑	1	
1-3		水口钳	1		2-3		右Z轴丝杆螺母支撑	1	
1-4		1.5M 电源线	1		2-4		导风嘴	1	
1-5		5mm*160mm 螺丝刀	1		2-5		1.6M 皮带	1	
1-6		包含以下四个部件	1		2-6		1.5M USB数据线	1	

序号	图片	零件名称	数量	核对	序号	图片	零件名称	数量	核对
1-6-1		40*10 风扇	1		2-7		5015 鼓风机	1	
1-6-2		40*11 散热片	1		2-8		Y轴皮带轴承支撑	1	
1-6-3		风扇保护罩	1		2-9		亚克力配件包含以下五个部件	1	
1-6-4		M3*45 螺丝 2个 M3 垫片 8片	1		2-9-1		Z轴限位开关固定块	2	
1-7		螺丝包含以下八个部分	1		2-9-2		Y轴电机支撑	1	
1-7-1		M3*18 螺丝 50个	1		2-9-3		Y轴限位开关固定块	1	
1-7-2		M3 螺母 60个	1		2-9-4		Y轴皮带固定夹	2	

序号	图片	零件名称	数量	核对	序号	图片	零件名称	数量	核对
1-7-3		M8 螺母 16个 M8 垫片 12片	1		2-9-5		导向杆挡片	6	
1-7-4		M4*8 螺丝 28个 M4*14 螺丝 4个	1		2-10		左右支撑板	2	
1-7-5		M3*30 螺丝 14个	1		2-11		料架支撑板	2	
1-7-6		M3*12 螺丝 15个	1		2-12		料架支撑板链接片	2	
1-7-7		M2*10 螺丝 4个 蝶形螺母 4个 弹簧 4个	1		2-13		屏幕保护板	1	
1-7-8		M3*20 螺丝 4个 M2.3*10螺丝 2个	1		2-14		Z轴电机支撑板	4	
1-8		包含以下三个部件	1		2-15		8GB TF卡和读卡器	1	

序号	图片	零件名称	数量	核对	序号	图片	零件名称	数量	核对
1-8-1		电线 70CM	1		3-1		下支撑板	1	
1-8-2		Z轴限位开关 1 20CM X轴限位开关 2 50CM Y轴限位开关 3 50CM	3		3-2		上支撑板	1	
1-8-3		塑料垫柱 M3*7 4个 塑料垫柱 M3*15 4个	8		3-3		后固定板	1	
1-9		包含以下三个部件	1		3-4		前固定板	1	
1-9-1		3mm*130mm 十字螺丝刀	1		3-5		支撑板锁板	2	
1-9-2		内六角扳手 M1.5 内六角扳手 M2 内六角扳手 M2.5 内六角扳手 M3	4		3-6		左右Z轴电机固定板	2	
1-9-3		开口扳手	1		3-7		Y轴电机固定板	1	

序号	图片	零件名称	数量	核对	序号	图片	零件名称	数量	核对
1-10		包含以下四个部件	1		3-8		挤出机	1	
1-10-1		4.5M 绕线管	1		3-9		X轴电机	1	
1-10-2		扎带	10		3-10		Y轴电机	1	
1-10-3		R型夹	3		3-11		Z轴电机	2	
1-10-4		定位片	2		3-12		直线滑块	7	

序号	图片	零件名称	数量	核对	序号	图片	零件名称	数量	核对
1-11		2004LCD控制屏	1		3-13		X轴导向杆 8*436mm 2根 Y、Z导向杆 8*380mm 4根	6	
1-12		X轴电机线 40CM Y轴电机线 40CM 左Z轴电机线 40CM 右Z轴电机线 90CM 挤出机电机电线 90CM	5		3-14		4头T形丝杆 M8*345mm 2根 螺纹杆 M8*400mm 2根 螺纹杆 M8*150mm 1根	5	
1-13		热床线 90CM	1		3-15		电源 12V 20A 240W	1	