



Each PCB contains two such circuits. They share power, GND and the 6 connections marked A,B,C,D,E,F. A cable connects these 6 points to their counterparts on the second PCB.

CNC AXIS CONTROLLER (1 of 2 identical PCBs)
Brian Millier March 18, 2012