





Safety Instructions

1.2.3.4.5.6.7.8.9. 11.12.13.14.
15.16.17.18.19.20.21.22.23.
25.26.27.28a.28b.29.30.31.34







Paulmann Licht GmbH

Quezinger Feld 2
D-31832 Springe

www.paulmann.com

+49 (0) 5041 998 389

Mon.-Do. ☺ 7⁰⁰-20⁰⁰
Fr. ☺ 7⁰⁰-17⁰⁰



Transfo Mipro S 80VA




SAFETY INSTRUCTIONS
Nr.28a/b !!

Ta: 45°C




SAFETY INSTRUCTIONS
Nr. 28a !!

Tc: 75°C




12V SEC



- H03VVH2-F
 - H03VV-F
 - H05VVH2-F
 - H05VV-F
- min. 2x 0,75mm²

- H03VVH2-F
 - H03VV-F
 - H05VVH2-F
 - H05VV-F
- min. 2x 0,75mm²



Transfo Mipro S 105VA



SAFETY INSTRUCTIONS
Nr.28a/b !!

Ta: 40°C




SAFETY INSTRUCTIONS
Nr. 28a !!

Tc: 75°C



12V SEC



- H03VVH2-F
 - H03VV-F
 - H05VVH2-F
 - H05VV-F
- min. 2x 0,75mm²

- H03VVH2-F
 - H03VV-F
 - H05VVH2-F
 - H05VV-F
- min. 2x 0,75mm²

